



# HT10

## Temperature & Humidity Indicator

### FEATURES

- ❖ Indoor and outdoor temperature display
- ❖ Indoor humidity display
- ❖ °C / °F selectable
- ❖ Frost point alarm -1 ~ 4°C (30.2 ~ 39.2°F)
- ❖ Memorized max & min temperature
- ❖ Back stand & magnetic stick

### SPECIFICATIONS

Indoor temp. range	: -10 ~ 50°C (14 ~ 122°F)
Outdoor temp. range	: -50 ~ 70°C (-58 ~ 158°F)
Indoor humidity	: 20 ~ 90% RH
Power	: 1.5V (AAA battery)
Size / weight	: 82 x 70 x 20mm / 66g

Constant Instruments  
P.O. BOX 435  
Joondalup, W.A. 6919  
Australia

For more information call :  
Fax : +61 8 93050111  
Email : sales@constantinstruments.com  
Website : www.constantinstruments.com



© 2017 Constant Instruments  
All rights reserved. 062017B01. Specifications subject to change without prior notice.

### TYPICAL APPLICATIONS

- ❖ Restaurant
- ❖ Production line
- ❖ Home



- ❖ Office



- ❖ Storage



- ❖ Laboratory

